



**Table 1: Soil Sampling Results for 4317 Clayton St**

Soil Sample Number	Date Sampled	Arsenic (parts per million)	Lead (parts per million)
3-90064-R	2/14/2003	5.2	270
3-90065-R	2/14/2003	5.5	200
3-90066-R	2/14/2003	8.7	270
Decision Value*		8.7	246.7

* The decision value for arsenic is a conservatively high estimate of the average concentration of arsenic in your yard. The decision value for lead is the average of the measured values for lead in your yard.

VB/I70 Phase III Soil Sampling Property Diagram

Property Address: 4317 Clay A — Property Number: _____



Sub Area	No. of Grids	Grid Area per Flag (APF)	No. of Flags in Sub Area (SubArea Grids + APF)
1	<u>75</u>	$225 / 7.5$	<u>10</u>
2	<u>75</u>		<u>10</u>
3	<u>75</u>		<u>10</u>
4	_____	(Total Grids ÷ 30)	_____
5	_____	<u>7.5</u>	_____
6	_____		_____
7	_____		_____
8	_____		_____
Total Grids:	<u>225</u>		Total Flags (30): <u>30</u>

Samplers' Signatures:

[Signature]

Date: 2/14/03 □

[Signature]

Date: 2/14/03

Surface Soil Data Sheet

Phase: Pilot Study

Medium: Surface Soil

Date: 2/11/03

Location: 4317 Clayton Property #: _____
(House #) (Street Name)

Building Type: Residential (circle one) Single Multifamily Apartment

School (name): _____

Park (name): _____

lot

Phase III Samples

Sample Number	Sample Time	Sample Depth
3-90064-R		0-2"
3-90064-R 3-90066-R		0-2"
3-90065-R		0-2"

Hazard Screen Samples

Hazard Screen Type: (circle one): Arsenic Lead

Sample Number / Location	Sample Time	Sample Depth

Notes: ~~3-90064-R~~ 3-90064-R

Samplers' Signatures:

[Signature]

Date: 2/14/03

[Signature]

Date: 2/14/03

MFG, Inc.

CHAIN-OF-CUSTODY RECORD AND REQUEST FOR ANALYSIS

COC No: 45903

☐ Arcata Office
1165 G Street, Suite E
Arcata, CA 95521-5817
Tel: (707) 826-8430
Fax: (707) 826-8437

☐ Boulder Office
4900 Pearl East Circle
Suite 300W
Boulder, CO 80301-6118
Tel: (303) 447-1823
Fax: (303) 447-1836

☐ Irvine Office
17770 Cartwright Road
Suite 500
Irvine, CA 92614-5850
Tel: (949) 253-2951
Fax: (949) 253-2954

☐ Osburn Office
P.O. Box 30
Wallace, ID
83873-0030
Tel: (208) 556-6811
Fax: (208) 556-7271

☐ San Francisco Office
71 Stevenson Street
Suite 1450
San Francisco, CA 94105-2941
Tel: (415) 495-7110
Fax: (415) 495-7107

☐ Seattle Office
19203 36th Avenue W.
Suite 101
Lynnwood, WA 98036-5707
Tel: (425) 921-4000
Fax: (425) 921-4040

PROJECT NO: 010107v-1 PROJECT NAME: VB/I-70 PAGE: 1 OF: 1
SAMPLER (Signature): [Signature] PROJECT MANAGER: Andy Koulermos DATE: 2/14/07
METHOD OF SHIPMENT: Hand CARRIER/WAYBILL NO: DESTINATION: Arcata

SAMPLES											ANALYSIS REQUEST									
Field Sample Identification	Sample		Preservation				Filtration*	Containers			Constituents/Method				Handling		Remarks			
	DATE	TIME	Matrix*	HCl	HNO ₃	H ₂ SO ₄		COLD	VOLUME (ml/oz)	TYPE*	NO.	Pb (6010)	As (6010)	Pb (3017)	As (7109)	HOLD		FUSH	STANDARD	
3-90064-R	2/14/03		60							1	✓	✓	✓	✓		✓		dry 15.00g (42mm) 5 day TAT		
3-90064-d																				
3-90065-R																				
3-90066-R																				
3-90067-R																				
3-90067-d																				
3-90068-R																				
3-90069-R																				
3-90070-E					✓		✓						✓	✓				5 day TAT		
TOTAL NUMBER OF CONTAINERS											9		LABORATORY COMMENTS/CONDITION OF SAMPLES							Cooler Temp:
RELINQUISHED BY:					DATE		TIME		RECEIVED BY:											
SIGNATURE	PRINTED NAME		COMPANY						SIGNATURE		PRINTED NAME		COMPANY							
<u>[Signature]</u>	<u>John McMahon</u>		<u>MFG</u>		<u>2/14/03</u>		<u>1330</u>		<u>[Signature]</u>		<u>B. H</u>		<u>AEL</u>							
LABORATORY																				

*KEY Matrix: AQ - aqueous NA - nonaqueous SO - soil SL - sludge P - petroleum A - air OT - other Containers: P - plastic G - glass T - teflon B - brass OT - other Filtration: F - filtered U - unfiltered
DISTRIBUTION: PINK: Field Copy YELLOW: Laboratory Copy WHITE: Return to Originator



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18th STREET - SUITE 500
DENVER, CO 80202-2466
<http://www.epa.gov/region08>

ACCESS AGREEMENT

I will allow EPA staff and EPA's authorized representatives to have access to my property(ies) located at 4317 Clayton, 3784 Franklin for the purpose of collectiong soil samples. I understand that this service is provided at no cost to me.

I understand that this soil testing is part of an investigation of possible metals contamination in residential soils in the Vasquez Boulevard and Interstate 70 Superfund Site. EPA is conducting this investigation as part of its responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (Superfund).

This written permission is given by me voluntarily.

2-14-03 William L. Hull 303 936-3361
Date Signature Phone Number

☒ I would like to be present during the sampling. My daytime telephone number is 303 936 3361

Comments:

Soil sampling will take no longer than 1 day. It is not necessary that the owner or resident be present. However, if you would like to be present, please let us know when you will be home and provide us with your daytime telephone number. You may also use the comment section to tell us special information about your property (for example, "be careful not to let dog out of the back yard"). Thank you for participating in this important study of your neighborhood.